

CHANGES TO THE DRAWING:

Fig. 3 has been amended to replace the erroneous reference number "76" with the correct reference number "46."

A replacement sheet with the corrected Fig. 3 is attached.

OIPF
AUG 27 2004

Replacement Sheet
Title: LOUDSPEAKER DRIVER
Inventor(s): Andreas BUOS et al.
Appl. No.: 09/986,115

Fig 3




Fig 5

